



# HARRISBURG PARK



November 2019

# OVERVIEW

- SUMMARY OF WORK TO DATE
- LOOK AHEAD
- PERMITTING & INSPECTIONS
- JOB SITE PROGRESS PHOTOS

November 2019



# SUMMARY OF WORK TO DATE

- CLEARING & GRUBBING
- SEDIMENT POND CONSTRUCTION
- OCS STRUCTURE & PIPE INSTALLED
- PHASE I EROSION CONTROL
- EXISTING ELECTRICAL SERVICE- DISMANTLED
- MATERIAL PROCUREMENT FOR STORM DRAINAGE & UTILITY
- DEMOLITION OF EXISTING MAINTENANCE SHED

November 2019



# PROJECT LOOK AHEAD

## WORK IN PROGRESS

- TOP SOIL STRIPPING
- CUT/FILL AT Z-MAX AND FIELD # 5 AREA
- STAKING FOR SEWER LINE INSTALLATION
- MOCK-UP PANEL

## WORK SCHEDULED TO BEGIN

- SEWER LINE INSTALLATION & ABANDONMENT
- STORM DRAINAGE INSTALL
- RETAINING WALL AT POND (WALL # 5) and BUILDING E WALL (# 10)
- CUT / FILL ZMAX WEST
- CUT / FILL EAST SIDE FIELDS

November 2019



# PERMITTING & INSPECTIONS

## PERMITTING

- CLEARING PERMITS – ISSUED
- GRADING PERMITS – ISSUED
- BUILDING PERMITS – ISSUED
- RETAINING WALL PERMITS – ISSUED
- MEP TRADE PERMITS - ISSUED

## INSPECTIONS

- EROSION CONTROL INSPECTIONS – CURRENT
- JOBSITE OFFICE POWER SERVICE

November 2019



# JOB SITE PROGRESS PHOTOS



FULL SITE PROGRESS PHOTO

November 2019



# JOB SITE PROGRESS PHOTOS



FUTURE FIELDS

November 2019



# JOB SITE PROGRESS PHOTOS



FUTURE FIELDS

November 2019



# JOB SITE PROGRESS PHOTOS



FUTURE AMPHITHEATER, PLAYGROUND, & SPLASH PAD AREA

November 2019



# JOB SITE PROGRESS PHOTOS



MASS GRADING

November 2019



# JOB SITE PROGRESS PHOTOS



MASS GRADING

November 2019

# JOB SITE PROGRESS PHOTOS



SEDIMENT POND

November 2019



# JOB SITE PROGRESS PHOTOS



STORM DRAIN MATERIAL PROCURMENT

November 2019



# JOB SITE PROGRESS PHOTOS



OCS STRUCTURE-2

November 2019

# JOB SITE PROGRESS PHOTOS



OCS STRUCTURE-2 + FES 1 INSTALLATION

November 2019



# JOB SITE PROGRESS PHOTOS



FES 1 INSTALLATION

November 2019

# JOB SITE PROGRESS PHOTOS



MOCK UP PANEL PROGRESS

November 2019

